

**North Bank Playground****Completed By: Patrick McCord****Date of Report: March 03, 2020****Time of Observation: 1:00 PM**

EATHER							
	Clear	PM	Calm		<10 deg		61-70 deg
PM	P/Cloudy		Slight Breeze		11-20 deg		70-80 deg
	Overcast		Moderate Winds		21-32 deg		80-90 deg
	Rain		Windy		33-45 deg		91-99 deg
	Smokey		Very Windy +35mph	PM	45-60 deg		100+
	Snow						
2. CONSTRUCTION ACTIVITY							
Area	Observation						
Site	Asphalt paving being demolished and removed from existing parking lot. Existing stormwater inlets and communication vault being removed. Petroleum soils have been excavated and hauled off site. Parking lot being excavated to subgrade. North/south footing lines being excavated. Staples being removed from large shelter roof; bird screen has been removed.						
Building	No work.						
3. LABOR (REPORTED FROM GENERAL CONTRACTOR)							
Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers
T LaRiviere	6		0		0		
4. EQUIPMENT ON SITE							
Type of Equipment	#	Type of Equipment	#	Type of Equipment	#	Type of Equipment	#
Compaction roller	1	Dozer	1	Track hoe	3		
Terex dumptruck	1	Front loader	0	Water truck	1		
Bobcat	1	Extended forklift	1	Track hoe with hammer	1		
Man lift	0	Mini track hoe	1	Extended manlift	1		
5. TPZ							
<ul style="list-style-type: none"> Fencing has been reinstalled. 							
6. DELIVERIES & CONDITIONS Note time and type of delivery							
<ul style="list-style-type: none"> 							
7. FIELD DISCUSSIONS OR NOTES (provide bulleted list of discussions, directions or decisions)							
<ul style="list-style-type: none"> 							
8. SCHEDULE REVIEW							
<ul style="list-style-type: none"> 							
9. PROJECT PHOTOGRAPHS							
<ul style="list-style-type: none"> See pictures below: 							



North Bank Playground

Completed By: Patrick McCord

Date of Report: March 03, 2020


Time of Observation: 1:00 PM



#1 View from cliff east side of the cliff (facing south)



#2 View from east side of the cliff (facing west)



#3 View from west side of the cliff (facing east)



#4 Area of petroleum soils removal.



#5 View from southeast corner (facing west)..



#6 Large shelter.



7 Existing parking lot.



#8 Standing water in the petroleum area..



#9 Demolished stormwater inlets.